



ACIS 7303

Avaya CallPilot(TM) Implementation Exam

Thank You for Downloading 7303 Updated Exam Questions

<https://certs4sale.com/avaya/7303-pdf-exam-dumps>

Question: 1

A technician is installing a 600r, and notices that the server boots to the Windows screen then starts booting again. It is stuck in a boot. What is the first step that should be taken?

- A. Re-image the server.
- B. Open a case requesting a replacement server.
- C. Replace the hard drive.
- D. Verify the SCSI terminator or tape drive is properly connected to the server.

Answer: B

Question: 2

A technician has completed the configuration and programming for an implementation of a new Avaya CallPilot system. When the Avaya CallPilot is rebooted, over which local Area Network (LAN) connection does the Communication Server 1000 communicate with the Avaya CallPilot voicemail system?

- A. DSO
- B. CLAN
- C. ELAN
- D. SLAN
- E. TLAN

Answer: C

Question: 3

A company is planning to install a new Avaya CallPilot RIs. 5.0 system. They need a high availability system that will allow a standby server to take over in case the primary server fails. Which hardware platform should be delivered on-site?

- A. 703t
- B. 600r
- C. 1006r
- D. 1002rp
- E. 2250

Answer: C

Question: 4

A technician is installing an Avaya CallPilot with the NTRH40CA MBP96 CAT5 board and two NTRB18DA Mgate cards. When cabling the NTRB18DA Mgate cards in a Communication Server 1000S Media Gateway, which statement describes the cabling configuration that is the most valid?

- A. Attach the customer supplied RJ-45 cables to the face of the Mgate cards and then to the MBP96 card.
- B. Attach the customer supplied RJ-45 cables to the backplane of the Media Gateway or Media Gateway expansion cabinet and then to the MBP96 card.
- C. Attach NTDU0609 cables to the face of the Mgate cards and route them outside the Media Gateway. Then couple the customer supplied RJ-45 cables from the NTDU0609 to the MPB96 cards.
- D. Attach the NTDU0609 cables to the face of the Mgate cards and take them outside the Media Gateway to a customer supplied Ethernet hub. Attach RJ-45 cable from the hub to the MPB96 cards.

Answer: C

Question: 5

Which two additional software packages are installed during the Avaya CallPilot Reporter installation?

- A. Adobe Acrobat
- B. Crystal Reports
- C. Application Builder
- D. a Sybase database

Answer: B,D

THANK YOU FOR DOWNLOADING 7303 UPDATED EXAM QUESTIONS

Note: Thanks For Trying The Demo Of Our 7303 Exam Product

Visit Our Site to Purchase the Full Set of Actual 7303 Exam Questions With Answers.

Money Back Guarantee



Click The Link Below

<https://certs4sale.com/avaya/7303-pdf-exam-dumps>