



EMCIE E20-340

CLARiiON Solutions Implementation

Thank You for Downloading E20-340 Updated Exam Questions

<https://certs4sale.com/dell-emc/e20-340-pdf-exam-dumps>

Question: 1

What do drives 0_0_0 to 0_0_4 in a CX4 contain?

- A. FLARE and vault
- B. Linux OS and metadata
- C. DART and vault
- D. Enginuity and metadata

Answer: A

Question: 2

What is a characteristic of disk-drive Spin Down?

- A. Spin Down is only available on CX4.
- B. Drives 0-4 are eligible for Spin Down.
- C. Drive Spin Down is available for thin LUNs.
- D. Drive Spin Down is available for all drives.

Answer: A

Question: 3

What is the maximum number of disk drives that can be configured in a pool on a CX4-480?

- A. 475
- B. 16
- C. 480
- D. 32

Answer: A

Question: 4

A customer currently has four CLARiiON arrays installed. They would like you to implement ESRS. What monitoring environment is a prerequisite for installing ESRS?

- A. Centralized Monitoring
- B. Distributed Monitoring
- C. Storage Processor Email Monitoring
- D. Host Based SNMP Monitoring

Answer: A

Question: 5

A customer would like to configure NTP using Unisphere. What is the minimum polling time allowed for NTP?

- A. 30 minutes
- B. 60 minutes
- C. 15 minutes
- D. 10 minutes

Answer: A

Question: 6

What communication protocol does Unisphere use?

- A. SSL
- B. SFTP
- C. UDP
- D. SSH

Answer: A

Question: 7


A customer has a CX4 series CLARiiON and is experiencing a problem with SPA . Upon arrival you notice that the SPA Fault LED is amber and flashing at a rate of four times a second. What is the boot state of SPA?

- A. POST Starting OS
- B. OS Booted
- C. Executing BIOS
- D. FLARE Driver Complete

Answer: A

Question: 8

Refer to the exhibit.



What is the correct order of the management module components?

- A. A-GbE Service LAN; B-GbE Management LAN; C-Service Port COM1; D-SPS Port COM2; ENMI Button
- B. A-GbE Management LAN; B-GbE Service LAN; C-Service Port COM1; D-SPS Port COM2; ENMI Button
- C. A-SPS Port COM2; B-NMI Button; C-Service Port COM1; D-GbE Service LAN; E-GbE Management LAN
- D. A-GbE Service LAN; B-GbE Management LAN; C-SPS Port COM2; D-Service Port COM1; EEMC NMI Button

Answer: A

Question: 9

Which statement accurately describes DAE3P enclosures?

- A. Supported on CX3 and CX4 series arrays
- B. Support the 2 Gb/s LCC card
- C. Contain 14 disk drives
- D. Support FC, ATA, Flash drives, and SATA-II drives

Answer: A

Question: 10

How many front-end ports are required to provide failover between SPs for eight direct-attached hosts on a CX4?

- A. 16

- B. 8
- C. 4
- D. 2

Answer: A

Question: 11

A customer has installed a new CX4 and is using ALUA SCSI communications with a Windows 2008 server and PowerPath. The server is using two LUNs on the array and they are both owned by SPA . Which statement describes how I/O is handled when a host has two paths to each SP, and there are no faults in this environment?

- A. I/O will flow to the owning SP over the optimal paths.
- B. I/O will flow to each SP and load balance all paths.
- C. I/O will flow on only one path to each SP even if multiple paths are defined.
- D. I/O flows to the owning SP and then will use the CMI bus for additional I/O.

Answer: A

Question: 12

What connectivity rules should be applied when configuring storage processor management ports on a CX4?

- A. Both ports must be on the same subnet.
- B. Both ports must be connected via CAT 5 cabling.
- C. Both ports must be connected via 10/100 Ethernet.
- D. Both ports must be directly connected to the host.

Answer: A

THANK YOU FOR DOWNLOADING E20-340 UPDATED EXAM QUESTIONS

Note: Thanks For Trying The Demo Of Our E20-340 Exam Product

Visit Our Site to Purchase the Full Set of Actual E20-340 Exam Questions With Answers.

Money Back Guarantee



Click The Link Below

<https://certs4sale.com/dell-emc/e20-340-pdf-exam-dumps>